



Ford Courier / Escort (III, IV, V, VI, VII) / Express / Fiesta (I, II, III) / Orion (I, II, III)

Exception: transmission type MTX75

Art. no. 3100 025 001

The following defects may occur with the aforementioned vehicles:

- Clutch release bearing makes knocking noises
- Stiff clutch actuation

Possible cause:

The plastic housing of the clutch release bearing has worked its way into the aluminum guide sleeve.

→ Apply repair kit 3100 025 001.



NOTE

The clutch release bearing no longer fits through the larger diameter of the steel guide sleeve.
→ Install a clutch release bearing with a suitable diameter.

Guide sleeve assembly

1. Place a suitable tool on the collar of the guide sleeve.
2. Drive the steel guide sleeve onto the aluminium guide sleeve.



NOTE

Since 02.1995 Ford has deployed a steel guide sleeve in volume production and when overhauling transmissions (95WT 7F 096-AA →).



www.zf.com/serviceinformation