



AUDI / SEAT / SKODA / VOLKSWAGEN



Possible Causes:

- Deteriorated guide of the push rod in the input shaft
- Excessive play of the input shaft bearing
- Another potential cause is a defective release bearing

Consequences:

- Drag
- Noise
- Judder
- Stiff actuation
- Clutch slip

NOTICE

Carefully inspect the described parts when replacing the clutch and renew them if necessary. If signs of eccentric contact caused by the push rod are visible, the described bearings are defective and **must** be replaced.



www.zf.com/serviceinformation