



Audi	A4 (→ 2008) / A5 (→ 2008) / ...
-------------	---------------------------------



The vehicle manufacturer has changed the release system.
Identifying feature: diameter of the guide tube.



If the clutch release bearing and components of the release system do not fit together, errors can occur:

- Engine does not start
- Clutch does not work
- No entries available in error memory.

NOTICE

Material damage may occur.

- Before assembly, check whether repairs on the clutch have previously been carried out on the vehicle. Do the clutch release bearing and the components of the release system (fork, guide tube, dog point, etc.) fit together?
- If necessary, replace all components in the release system with parts that are type Ø 36 mm (Tab. 1).

	Guide tube		Quantity
	Ø 34 mm	Ø 36 mm	
Clutch release bearing	3151 271 937	---	1
Clutch release bearing with guide tube	---	3189 600 062	1
Clutch release fork	---	0B1 141 719 K	1
Screw	---	N910 967 02	2
Dog point	---	0B1 141 777 B	1
Adapter	---	0B1 141 751	1

Tab. 1: Item numbers



www.aftermarket.zf.com/serviceinformation