



Scania



Fig. 1: Replaced air spring 27-C33-0



Fig. 2: Current air spring 27-F97-0

The air spring 27-C33-0 was replaced by the air spring 27-F97-0.
The design of the upper cap was changed (Fig. 1, Fig. 2).



The replacement of the air springs is possible **without** modification.
The air springs can only be installed with SACHS or BOGE driver's cabin dampers.
A combination with driver's cabin dampers from other manufacturers is **not** possible.



www.zf.com/serviceinformation