



Alfa Romeo 147 (937) / 156 (932) / GT (937) / ...




Fig. 1: Control arm

- 1 Control arm
- 2 Self-locking nut
- 3 Metal core
- 4 Rubber bearing



The metal core (3) is not vulcanized with the rubber bearing (4). Therefore, the metal core is rotary. This is constructively intended.

During assembly, always use a new self-locking nut (2) and tighten using the stipulated tightening torque.

Observe the information provided by the vehicle manufacturer.



www.zf.com/serviceinformation