



Sl. 1: Stapajica s utomom



Sl. 2: Stapajica bez utora



U stapajicu je urezan jedan utom zbog proizvodnog postupka (sl. 1). Amortizeri sa ili bez utora (sl. 2) u stapajici, konstrukcijski su isti. Obje izvedbe se mogu ugraditi na istoj osovini.



www.zf.com/serviceinformation