



Scania



Fig. 1: Replaced air spring 557 001



Fig. 2: Current air spring 310 619

The air spring 557 001 was replaced by the air spring 310 619.
The design of the upper cap was changed (Fig. 1, Fig. 2).



The replacement of the air springs is possible **without** modification.
The air springs can only be installed with SACHS or BOGE driver's cabin dampers.
A combination with driver's cabin dampers from other manufacturers is **not** possible.



www.zf.com/serviceinformation