

TRW Service Kit JBJ174

The Service Kit JBJ174 contains a separate dust cover, which is fixed between steering knuckle and track control arm after installation.

Affected vehicles: Hyundai, Mitsubishi and Volvo



Note: The illustrations provided are typical and for guidance only.

After installation the ball joint must be fixed with the circlip supplied!

